


INSTALLATION GUIDE LAN-WMBUS-R4X-M-LR-X REV 1.0

MOUNTING








screws. Remove the cover.

Mount the device either using the pole mounting quipment or using 4 standard screws.

Connect the 230 V AC/DC cable to the two connectors. This must be done by trained professionals!







Make sure to tighten the cable gland so that it firmly holds the cable

Put back the cover and secure it by using the 4 plastic screws.

Make sure to use TX antennas without large gain due to output regulations. The RX antenna can be of any size.

Mount the desired antennas.